


FILLING VALVES

ARGO




description

- Filling charge valve
- Max working pressure: 260 bar
- Working temperature: -40°C +120°C
- Manual safety tap – available in different thread connections



product



certifications

ECE R110 - CERTIFIED

Outlet pipe connections	External bracket connections	Filling charge valve
M12X1	G" 1/2	ARGO000
1/4"NPT	G" 1/2	ARGO001
M14X1	G" 1/2	ARGO002
7/16 – 20 UNF	G" 1/2	ARGO003